

Clerk's Report – April 2025

1. SCC/AMEY HIGHWAYS REPORT UPDATES					
Date Reported	No	Description	Status	Update	Amey Action
31/03/23	4318970	Silver Lane - blocked gully	Works carried out	27/06/23	Inspection carried out, works raised
19/09/23	4343026	Church Lane - edge drop	3rd party works	29/09/23	Defect being monitored under routine inspections
11/08/23	4338717	Church Lane - overgrown hedge blocking road sign	Unable to action	11/08/23	3rd party works being monitored
19/11/23	4351777	Moisty Lane - drain blocked	Ongoing	19/11/24	Work to be done when resources allow
12/01/24	4362579	Road edge disintegrated between Willow Grange and Wren Park	3rd party works	14/01/24	Being monitored
26/01/24	4365252	Windmill Drive pothole	Work raised	26/01/25	Work to be done when resources allow
26/01/24	4365251	Windmill Drive pothole	Work raised	26/07/24	Work to be done when resources allow
26/01/24	4365130	Pothole on Hall Road	Ongoing	26/01/25	Work to be done when resources allow
26/01/24	4365104	Moisty Lane - pothole at top of Windmill Drive	Ongoing	12/03/25	Inspection confirmed work taken place
19/02/24	4370679	Hall Road nr to Marchington Hall	Ongoing	19/02/25	Work to be done when resources allow
19/02/24	4370689	Hall Road nr to Marchington Hall	Ongoing	19/02/25	Work to be done when resources allow
19/02/24	4370693	Hall Road nr to The Poplars	Ongoing	19/02/25	Work to be done when resources allow
22/02/24	4371865	Bag Lane - verges	Ongoing	22/02/25	Work to be done when resources allow
17/05/24	4389203	Top of Silver Lane ST14 8LL area around drain collapsing	resident reported	09/07/24	Inspection carried out, works raised
23/05/24	4390407	Bag Lane - drain blocked by tarmac and red clay bank slippage	Reported	03/06/24	Inspection carried out, works raised
07/09/24	4405380	Moisty Lane - dead Ash Tree	resident reported	12/09/24	Landowner responsibility
15/10/24	4410637	Woodroffe's Cliff - pothole	Cllr Lord reported	14/01/25	Non-urgent work instruction raised.
15/10/25	4410641	Highwood	Cllr Lord reported	27/01/25	Non-urgent work instruction raised.
10/02/25	4428124	Marchington Cliff - potholes	Cllr Prince report	10/02/25	Marked up for attention
10/02/25	14485	Bridge at Fairford (B5017)	Cllr Prince report	07/04/25	Work complete
03/03/25	4431664	Marchington Cliff - blocked drain, gulley	Cllr Prince report	03/03/25	Clerk chased, works raised
10/03/25	4432837	Gorsty Hill to Highwood - multiple potholes	Cllr Lord reported	10/03/25	Report logged
	4433894	Stubby Lane Marchington - overgrown hedge (Ind Estate)	Clerk report	17/03/25	Liaison officer arranged inspection

a. Jacks Lane – speed humps, no update.

b. Cllr Atkins report on extra crews allocated to Marchington:

1. **Footpath Issues** – to receive any items of concern regarding footpaths
2. **South Staffordshire Water** – Asbestos mains concerns. *No response from SSW*
3. **Permissive Path Project** – no update.